

Eagle Home Inspections 2211 Durham Road Madison CT 06443 203-640-2053 ron@eagle-inspections.com

Inspection reference: Date and Client Name

Confidential Inspection Report

Inspection Address

Inspection Date



Prepared for:

Client Name

This report is the exclusive property of the inspection company and the client whose name appears herewith and its use by any unauthorized persons is prohibited.

Inspection Contents

Summary	3
GENERAL INFORMATION	5
GROUNDS	7
EXTERIOR - FOUNDATION	10
ROOF SYSTEM	12
GARAGE - CARPORT	15
BASEMENT - CRAWLSPACE	16
ELECTRICAL SYSTEM	17
HEATING - AIR CONDITIONING	19
PLUMBING SYSTEM	21
KITCHEN - APPLIANCES	23
BATHROOMS	24
INTERIOR ROOMS	25
LAUNDRY AREA	27

This summary page is not the entire report. The complete report may include additional information of interest or concern to you. It is strongly recommended that you promptly read the complete report. For information regarding the negotiability of any item in this report under the real estate purchase contract, contact your Connecticut real estate agent or an attorney."

Wednesday, Date of Inspection

Client Name



Inspection Address

Dear Client Name:

At your request, a visual inspection of the above referenced property was conducted on Date of Inspection An earnest effort was made on your behalf to discover all visible defects, however, in the event of an oversight, maximum liability must be limited to the fee paid. The following is an opinion report, reflecting the visual conditions of the property at the time of the inspection only. Hidden or concealed defects cannot be included in this report. No warranty is either expressed or implied. This report is not an insurance policy, nor a warranty service.

SUMMARY OF AREAS REQUIRING FURTHER EVALUATION

IMPORTANT: The Summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report. The entire Inspection Report, including the Standards of Practice, limitations and scope of Inspection, and Pre-Inspection Agreement must be carefully read to fully assess the findings of the inspection. This list is not intended to determine which items may need to be addressed per the contractual requirements of the sale of the property. Any areas of uncertainty regarding the contract should be clarified by consulting an attorney or real estate agent.

It is strongly recommended that you have appropriate licensed contractors evaluate each concern further and the entire system for additional concerns that may be outside our area of expertise or the scope of our inspection BEFORE the close of escrow. Please call our office for any clarifications or further questions.

Below is a list of items that need further evaluation or repair by appropriately Licensed Contractors.

GROUNDS

Paving Conditions:

Driveway:

Driveway Type: Asphalt, Cracks noted are typical.

Walks:

Sidewalk type: Paver/Tile, Surface raised/settled, Overgrown.

Retaining Walls:

Condition:

Retaining wall type: Wood. Peeling paint, deteriorated surfaces.

Landscaping:

Condition:

Foliage is overgrown and needs trimming. Trim plants away from structure leaving at least two feet of space. Trim all trees and limbs at least 10' away from structure. Trees planted close to structure. Removal/trimming may be needed. Trees/foliage touching the walls or overhanging the roof. Damage is possible.

EXTERIOR - FOUNDATION

Exterior Walls:

Materials & Condition:

Walls are constructed with Wood siding. Peeling paint.

Flashing & Trim:

Wood materials. Peeling paint.

Exterior Windows:

Overall Condition:

Broken thermal seals noted on both gable end windows (upstairs windows in finished room and atttic room).

Chimney:

Chimney Cap:

There is no chimney cap installed. Installation of a chimney cap is highly recommended to prevent water from entering the masonry stack or entering the wood chase causing deterioration.

ROOF SYSTEM

Roof:

Roof Covering Condition:

Moss and lichen growth. General condition appears serviceable with signs of normal aging. Regular maintenance and inspections are advised. A licensed roofing contractor should be called in to make further evaluation and to repair or replace as needed.

Skylights:

Broken thermal seal on skylight above stairs going to second floor.

GARAGE - CARPORT

Roof:

Condition:

See house roof report, Same as house. Moss and lichen growth on rear of roof. Trim back tree limbs and clean



debris off surface.

ELECTRICAL SYSTEM

Electrical Outlets:

General:

GFCI not functioning in master bathroom. Ground Fault Circuit Interrupter (GFCI) outlets are recommended for installation at exterior, garage, bath rooms & kitchen outlets.

Master Bath:

See electrical report, GFCI not operating as intended.

HEATING - AIR CONDITIONING

Heating Equipment:

General Operation & Cabinet:

No service record is evident. Service is due. Out of date. Corrosion noted around boiler component. Further Evaluation by an HVAC service is needed.

Fireplaces / Solid Fuel Heating:

BATHROOMS

Tub/Shower And Walls:

Upstairs Bath

Cracked gel coat in upstairs bathtub.

INTERIOR ROOMS

Ceilings:

General Type & Condition:

Crack noted on ceiling above entryway next to garage (outside of half bath).

Smoke / Fire Detector:

Comments:

Smoke and fire detectors have a limited life span of @ 10 years.. Replacing older units for safety is suggested.

Carbon Monoxide Detector:

Comments:

Add to all sleeping areas. At least one per level of the home.

Other minor items are also noted in the entire inspection report and should receive eventual attention, but do not affect the habitability of the house and the majority are the result of normal wear and tear.

Thank you for selecting our firm to do your pre-purchase home inspection. If you have any questions regarding the inspection report or the home, please feel free to call us.

Sincerely,

Ron Rivard

Eagle Home Inspections

GENERAL INFORMATION

Client & Site Information:

Inspection Date: Client: Inspection Site: People Present:

9:00 AM. Marley.

Building Characteristics:

Estimated Age: Building Style & Type: Stories: Space Below Grade:

1986 1 family. 2 Basement.

Water Source: Sewage Disposal: Utilities Status: Main Entry Faces:

Public. Public. All utilities on. Street.

Climatic Conditions:

Weather: Soil Conditions: Outside Temperature (f):

Overcast, Light Rain. Damp. 40-50.

About Rated Items:

Items not found in this report are beyond the scope of this inspection and should not be considered inspected at this time. Please read the entire report for important details. Inspected items may be generally rated as follows:

OK = "Serviceable" = Item is functional and we did not observe conditions that would lead us to believe problems existed with this system or component. Some serviceable items may show wear and tear. Other conditions may be noted in the body of the report.

MM = "Marginal/Maintenance" = Item warrants attention or monitoring, or has a limited remaining useful life expectancy and may require replacement in the not too distant future. Further evaluation or servicing may be needed by a qualified licensed contractor or specialty tradesman dealing with that item or system.

RR = "Repair or Replace" = Item, component, or unit is not functioning as intended and needs repair or replacement. Further evaluation is needed by a qualified licensed contractor or specialty tradesman dealing with that item or system.

NI = "Not Inspected/Not Present/Not Accessible"

REPORT LIMITATIONS

This report is intended only as a general guide to help the client make his own evaluation of the overall condition of the home, and is not intended to reflect the value of the premises, nor make any representation as to the advisability of purchase. The report expresses the personal opinions of the inspector, based upon his visual impressions of the conditions that existed at the time of the inspection only. The inspection and report are not intended to be technically exhaustive, or to imply that every component was inspected, or that every possible defect was discovered. No disassembly of equipment, opening of walls, moving of furniture, appliances or stored items, or excavation was performed. All components and conditions which by the nature of their location are concealed, camouflaged or difficult to inspect are excluded from the report. The inspection is performed in compliance with generally accepted standard of practice, a copy of which is available upon request.

Systems and conditions which are not within the scope of the inspection include, but are not limited to: formaldehyde, lead paint, asbestos, toxic or flammable materials, and other environmental hazards; pest infestation, playground equipment, efficiency measurement of insulation or heating and cooling equipment, internal or underground drainage or plumbing, any systems which are shut down or otherwise secured; water wells (water quality and quantity) zoning

ordinances; intercoms; security systems; heat sensors; cosmetics or building code conformity. Any general comments about these systems and conditions are informational only and do not represent an inspection.

The inspection report should not be construed as a compliance inspection of any governmental or non governmental codes or regulations. The report is not intended to be a warranty or guarantee of the present or future adequacy or performance of the structure, its systems, or their component parts. This report does not constitute any express or implied warranty of merchantability or fitness for use regarding the condition of the property and it should not be relied upon as such. Any opinions expressed regarding adequacy, capacity, or expected life of components are general estimates based on information about similar components and occasional wide variations are to be expected between such estimates and actual experience.

We certify that our inspectors have no interest, present or contemplated, in this property or its improvement and no involvement with tradespeople or benefits derived from any sales or improvements. To the best of our knowledge and belief, all statements and information in this report are true and correct.

Should any disagreement or dispute arise as a result of this inspection or report, it shall be decided by arbitration and shall be submitted for binding, non-appealable arbitration to the American Arbitration Association in accordance with its Construction Industry Arbitration Rules then obtaining, unless the parties mutually agree otherwise. In the event of a claim, the Client will allow the Inspection Company to inspect the claim prior to any repairs or waive the right to make the claim. Client agrees not to disturb or repair or have repaired anything which may constitute evidence relating to the complaint, except in the case of an emergency.

Predominant Type:

Exterior Windows: Vinyl double hung and double glazed.

GROUNDS

This inspection is not intended to address or include any geological conditions or site stability information. We do not comment on coatings or cosmetic deficiencies and the wear and tear associated with the passage of time, which would be apparent to the average person. However, cracks in hard surfaces can imply the presence of expansive soils that can result in continuous movement, but this can only be confirmed by a geological evaluation of the soil. Any reference to grade is limited to only areas around the exterior of the exposed areas of foundation or exterior walls. We cannot determine drainage performance of the site or the condition of any underground piping, including subterranean drainage systems and municipal water and sewer service piping or septic systems. Decks and porches are often built close to the ground, where no viewing or access is possible. Any areas too low to enter or not accessible are excluded from the inspection. We do not evaluate any detached structures such as storage sheds and stables, nor mechanical or remotely controlled components such as driveway gates. We do not evaluate or move landscape components such as trees, shrubs, fountains, ponds, statuary, pottery, fire pits, patio fans, heat lamps, and decorative or low-voltage lighting. Any such mention of these items is informational only and not to be construed as inspected.

Paving Conditions:

Driveway:

OK MM RR NI $\hfill\Box$ $\hfill\Box$ $\hfill\Box$ Driveway Type: Asphalt, Cracks noted are typical.





Walks:

OK MM RR NI

 $\hfill\Box$ \hfill $\hfill\Box$ $\hfill\Box$ Sidewalk type: Paver/Tile, Surface raised/settled, Overgrown.



Exterior Steps / Stoops:



Decks / Balcony:

Condition:

☑ □ □ Wood. No access below deck. Skirting around lower deck has fallen under deck.



Grading:

Site:

Retaining Walls:

Condition:

OK MM RR NI

☑ □ □ Flat site.

 $\hfill\Box$ \hfill $\hfill\Box$ $\hfill\Box$ Retaining wall type: Wood. Peeling paint, deteriorated surfaces.



Landscaping:

Condition:

□ □ □ □ □ Foliage is overgrown and needs trimming. Trim plants away from structure leaving at least two feet of space. Trim all trees and limbs at least 10' away from structure. Trees planted close to structure. Removal/trimming may be needed. Trees/foliage touching the walls or overhanging the roof. Damage is possible.





EXTERIOR - FOUNDATION

All structures are dependent on the soil beneath them for support, but soils are not uniform. Some that appear to be firm and solid can become unstable during seismic activity or may expand with the influx of water, moving structures with relative easy and fracturing slabs and other hard surfaces. In accordance with our standards of practice, we identify foundation types and look for any evidence of structural deficiencies. However, minor cracks or deteriorated surfaces are common in many foundations and most do not represent a structural problem. If major cracks are present along with bowing, we routinely recommend further evaluation be made by a qualified structural engineer. All exterior grades should allow for surface and roof water to flow away from the foundation. All concrete floor slabs experience some degree of cracking due to shrinkage in the curing process. In most instances floor coverings prevent recognition of cracks or settlement in all but the most severe cases. Where carpeting and other floor coverings are installed, the materials and condition of the flooring underneath cannot be determined. Areas hidden from view by finished walls or stored items cannot be judged and are not a part of this inspection. We will certainly alert you to any suspicious cracks if they are clearly visible. However, we are not specialists, and in the absence of any major defects, we may not recommend that you consult with a foundation contractor, a structural engineer, or a geologist, but this should not deter you from seeking the opinion of any such expert. We also routinely recommend that inquiry be made with the seller about knowledge of any prior foundation or structural repairs.

Exterior Walls:

	OIL	IVIIVI	1717	111		
Materials & Condition:		\checkmark			Walls are constructed with Wood siding.	Peeling paint.



Flashing & Trim: \checkmark Wood materials. Peeling paint.



Exterior Doors:

Main Entry Door: Side Entry Door: \square Rear Entry Door: \square Other Entry Doors: $\sqrt{}$

Exterior Windows:

Overall Condition: $\overline{\mathbf{Q}}$ Broken thermal seals noted on both gable end windows (upstairs windows in finished room and atttic room).





Type And Condition Of Sills:

Chimney:

Please Note:

There are a wide variety of chimneys and interrelated components. However, there are three basic types, single-walled metal, masonry, and pre-fabricated metal ones that are commonly referred to as factory-built ones. Single-walled metal ones should not be confused with factory-built metal ones, and are rarely found in residential use, but masonry and factory-built ones are commonplace. Our inspection of them conforms to industry standards, and is that of a generalist and not a specialist. However, significant areas of chimney flues cannot be adequately viewed during a field inspection. Therefore, because our inspection of chimneys is limited to areas easily viewed and does not include the use of specialized equipment, we will not guarantee their integrity or drafting ability and recommend that they be more thoroughly evaluated by a qualified

		chim	ney s	specia	alist b	efore the close of escrow.
	Chimney Exterior:	OK ☑	MM □	RR □	NI □	Chimney is constructed of brick materials.
	Flue:					
	Flashing:	\square				
	Chimney Cap:			☑		There is no chimney cap installed. Installation of a chimney cap is highly recommended to prevent water from entering the masonry stack or entering the wood chase causing deterioration.
Found	lation:					
	Materials & Condition:	\square				Concrete.
	Recent Movement:	Ther	e is n	o evi	dence	of any recent movement.
Utility	Connections: Exterior Walls:	$\overline{\mathbf{V}}$				

ROOF SYSTEM

Although not required to, we generally attempt to evaluate various roof types by walking on their surfaces. If we are unable or unwilling to do this for any reason, we will indicate the method used to evaluate them. Every roof will wear differently relative to its age, number of layers, quality of material, method of application, exposure to weather conditions, and the regularity of its maintenance. We can only offer an opinion of the general quality and condition of the roofing material.

The inspector cannot and does not offer an opinion or warranty as to whether the roof leaks or may be subject to future leakage. The waterproof membrane beneath roofing materials is generally concealed and cannot be examined without removing the roof material. Although roof condition can be evaluated, it is virtually impossible for anyone to detect a leak except as it is occurring or by specific water tests, which are beyond the scope of our service. Even water stains on ceilings or on framing within attics will not necessarily confirm an active leak without some corroborative evidence, and such evidence can be deliberately concealed. We evaluate every roof conscientiously, and even attempt to approximate its age, but we will not predict its remaining life expectancy, or guarantee that it will not leak. Naturally, the sellers or the occupants of a residence will generally have the most intimate knowledge of the roof and of its history. Therefore, we recommend that you ask the sellers about it, and that you either include comprehensive roof coverage in your home insurance policy, or that you obtain a roof certification from an established local roofing company. We do not

inspect attached accessories including by not limited to solar systems, antennae, and lightning arrestors.

Roof:

Style: Gable.

Roof Access: Ground view. Viewed from window.





Roof Covering:

Composition shingles, Architectural heavy duty design. Moss/Lichen growth. Can be damaging to the surface. Decreases the roof life span. Clean debris from surface.

OK MM RR NI

 \checkmark

Roof Covering Condition:

Moss and lichen growth. General condition appears serviceable with signs of normal aging. Regular maintenance and inspections are advised. A licensed roofing contractor should be called in to make further evaluation and to repair or replace as needed.




Flashings:

Sky	lig	hts
-----	-----	-----

OK MM RR N	OK	MM	RR	NI
------------	----	----	----	----

□ □ □ Broken thermal seal on skylight above stairs going to second floor.



Gutters & Downspouts:

Type & Condition:

□ □ □ □

In accordance with our standards, we do not attempt to enter attics that have less than thirty-six inches of headroom, are restricted by ducts, or in which the insulation obscures the joists and thereby makes mobility hazardous, in which case we would inspect them as best we can from the access point. In regard to evaluating the type and amount of insulation on the attic floor, we use only generic terms and approximate measurements, and do not sample or test the material for specific identification. Also, we do not disturb or move any portion of it, and it may well obscure water pipes, electrical conduits, junction boxes, exhaust fans, and other components.

Attic & Insulation:

Access:

Used as living space, Completely finished. One room/closet kept unfinished, used as storage area. Stored Items. Limiting access.

Attic access over garage is separate.








Structure:	☑		A rafter system is installed in the attic cavity to support the root decking.
Insulation:			Blown in fiberglass.
Ventilation Provisions:	V		There are ridge vents installed. There are soffit vents installed. There are gable end vents installed.

GARAGE - CARPORT

Determining the heat resistance rating of firewalls is beyond the scope of this inspection. Flammable materials should not be stored within closed garage areas. Garage door openings are not standard, so you may wish to measure the opening to ensure that there is sufficient clearance to accommodate your vehicles. It is not uncommon for moisture to penetrate garages, particularly with slabs on-grade construction, and this may be apparent in the form of efflorescence or salt crystal formations on the concrete. You may want to have any living space above the garage evaluated further by a structural engineer, as it may be seismically vulnerable.

Type:

Attached, One car, Stored items, areas not visible.



Roof:	OK MM RR NI
Condition:	☐ ☑ ☐ ☐ See house roof report, Same as house. Moss and lichen growth on rear of roof. Trim back tree limbs and clean debris off surface.
Ceilings: Condition:	
Garage Door:	

CCIIII	ıgə.
	Condi

Material - Condition:

 $\overline{\mathbf{Q}}$

Windows:

Door Operator:

Service Doors:

"Above the Rest	· N					
	Condition:					
Garag	e Walls:					
	Type & Condition: Fire Wall	OK ☑ ☑	MM	RR	NI	
Floor:						
	Condition:	V				Concrete.
	BAS	SE	ME	ĪΝ٦	Γ-	CRAWLSPACE
the inspor	pection, the inspector does not nents or be dangerous to or adve	ente	r any	area	a or	concern, some areas can go unnoticed. During the course o perform any procedure that may damage the property or its alth of the inspector or other persons.
Basen	n ent: Access:	V				Basement is finished for living.
	Walls:	N N				No. There were no elevated mainture levels noted on the exposed
	Moisture:	✓				No - There were no elevated moisture levels noted on the exposed areas of the basement walls.
	Beams/Underfloor:	Ø				Underfloor support beams are wood. The main beam is made o layered dimensional lumber sandwiched together creating a built-up beam.
			h .			

Posts/Piers & Columns:

□ □ □ Support posts are Steel.

ELECTRICAL SYSTEM							
Windows:	_	MM					
Floor:	\square				Carpet at finished areas.		
"Above the Rest" PF							

We are not electricians and in accordance with the standards of practice we only test a representative number of switches and outlets and do not perform load-calculations to determine if the supply meets the demand. However, every electrical deficiency or recommended upgrade should be regarded as a latent hazard that should be serviced as soon as possible, along with evaluation and certification of the entire system as safe by a licensed contractor. Therefore, it is essential that any recommendations that we may make for service or upgrades should be completed before the close of escrow, because an electrician could reveal additional deficiencies or recommend additional upgrades for which we disclaim any responsibility. Any electrical repairs or upgrades should be made by a licensed electrician. Aluminum wiring requires periodic inspection and maintenance by a licensed electrician. Smoke Alarms should be installed within 15 feet of all bedroom doors, and tested regularly.

Operation of time clock motors is not verified. Inoperative light fixtures often lack bulbs or have dead bulbs installed. The inspector is not required to insert any tool, probe, or testing device inside the panels, test or operate any over-current device except for ground fault interrupters, nor dismantle any electrical device or control other than to remove the covers of the main and auxiliary distribution panels. Any ancillary wiring or system that is not part of the primary electrical distribution system is not part of this inspection but may be mentioned for informational purposes only, including but not limited to low voltage systems, security system devices, heat detectors, carbon monoxide detectors, telephone, security, cable TV, intercoms, and built in vacuum equipment.

_						
<u>.</u>	Λ	r۱	/1	^	\mathbf{a}	-
J	ㄷ	ı١	,,	L	ㄷ	_

Type & Condition:			110/220 Volt, Circuit breakers
Grounding Equipment:			

Electrical Distribution Panels:

Main Panel Location: Basement.



Main Circuit Rating: 200 amps.

Service Disconnect Switch: Located at the top of main panel.



Main Panel Observations: ☑ □ □ □



OK MM RR NI

Subpanels:

☑ □ □ □ Subpanel located in the garage.



Cond	uctors:				
	Entrance Cables:				Aluminum.
	Branch Wiring:				Copper.
Switc	hes & Fixtures:				
	General:				A representative sampling of switches was tested. As a whole, switches throughout the house are in serviceable condition.
	Garage Walls:				
	Basement:				
	Master Bath:				
	Hall Bath:				
	Upstairs Bath				
	Basement Bath:				
Electr	ical Outlets:				
	General:		Ø		GFCI not functioning in master bathroom. Ground Fault Circuit Interrupter (GFCI) outlets are recommended for installation at exterior, garage, bath rooms & kitchen outlets.
		-		-	



 Exterior Walls:
 □
 □
 □

 Garage Walls:
 □
 □
 □

FACE Eraser Free In Home Inspections "Now the Rest"	nspect	ion:			Address:
Basement:	$\overline{\mathbf{V}}$				
	OK	MM	RR	NI	
Master Bath:		\checkmark			See electrical report, GFCI not operating as intended.
Hall Bath:					
Upstairs Bath	$\overline{\checkmark}$				
Basement Bath:					
Attic Wiring:					

HEATING - AIR CONDITIONING

The inspector can only readily open access panels provided by the manufacturer or installer for routine homeowner maintenance, and will not operate components when weather conditions or other circumstances apply that may cause equipment damage. The inspector does not light pilot lights or ignite or extinguish solid fuel fires, nor are safety devices tested by the inspector. The inspector is not equipped to inspect furnace heat exchangers for evidence of cracks or holes, or inspect concealed portions of evaporator and condensing coils, heat exchanger or firebox, electronic air filters, humidifiers and de-humidifiers, ducts and in-line duct motors or dampers, as this can only be done by dismantling the unit. This is beyond the scope of this inspection. Thermostats are not checked for calibration or timed functions. Adequacy, efficiency or the even distribution of air throughout a building cannot be addressed by a visual inspection. Have these systems evaluated by a qualified individual. The inspector does not perform pressure tests on coolant systems, therefore no representation is made regarding coolant charge or line integrity. We perform a conscientious evaluation of the system, but we are not specialists.

Please note that even modern heating systems can produce carbon monoxide, which in a poorly ventilated room can result in sickness and even death. Therefore, it is essential that any recommendations we make for service or further evaluation be scheduled before the close of escrow, because a specialist could reveal additional defects or recommend further upgrades that could affect your evaluation of the property, and our service does not include any form or warranty or guarantee. Normal service and maintenance is recommended on a yearly basis. Determining the presence of asbesto scope s inspec

Heatir

Attic & Insulation:

of this inspection. Determining t	he c	onditi	on o	f oil t	n ONLY be preformed by laboratory testing and is beyond the anks, whether exposed or buried, is beyond the scope of this azard which is sometimes costly to remedy.
ng Equipment:	_				
Type & Location:	Ford	ced ho	ot wat	er bo	ller.
		The state of the s			
Fuel Source:	\checkmark				Oil.
Capacity / Approx. Age:	200	6 unit			
General Operation & Cabinet:			V		No service record is evident. Service is due. Out of date Corrosion noted around boiler component. Further Evaluation be an HVAC service is needed.



Normal Controls:

OK MM RR \checkmark

There are multiple thermostats. The structure is divided into zones.

Fireplaces / Solid Fuel Heating:

Fireplace appears functional. Annual inspection and cleanings are needed when using these systems. Cleaning and further inspection by a professional before first use is needed. (Metal trim around glass door is loose at bottom, may need some adjustment or tightening to secure properly).





Auxiliary Equipment:

Whole House Attic Fan:

OK MM RR

□ □ □ ☑ Switch at top of stairs on wall.





PLUMBING SYSTEM

Water quality or hazardous materials (lead) testing is available from local testing labs, and not included in this inspection. All underground piping related to water supply, waste, or sprinkler use are excluded from this inspection. Leakage or corrosion in underground piping cannot be detected by a visual inspection, nor can the presence of mineral build-up that may gradually restrict their inner diameter and reduce water volume. Plumbing components such as gas pipes, potable water pipes, drain and vent pipes, and shut-off valves are not generally tested if not in daily use. The inspector cannot state the effectiveness or operation of any anti-siphon devices, automatic safety controls, water conditioning equipment, fire and lawn sprinkler systems, on-site water quality and quantity, on-site waste disposal systems, foundation irrigation systems, spa and swimming pool equipment, solar water heating equipment, or observe the system for proper sizing, design, or use of materials.

The water pressure within pipes is commonly confused with water volume, but whereas high water volume is good high water pressure is not. Therefore a regulator is recommended whenever street pressure exceeds 80 psi. However, regardless of pressure, leaks will occur in any system, and particularly in one with older galvanized pipes, or one in which the regulator fails and high pressure begins to stress washers and diaphragms within various components.

Waste and drainpipes pipe condition is usually directly related to their age. Older ones are subject to damage through decay and root movement, whereas the more modern ABS ones are virtually impervious to damage, although some rare batches have been alleged to be defective. Older homes with galvanized or cast iron supply or waste lines can be obstructed and barely working during an inspection but later fail under heavy use. If the water is turned off or not used for periods of time (such as a vacant house waiting for closing), rust or deposits within the piping can further clog the piping system. However, inasmuch as significant portions of drainpipes are concealed, we can only infer their condition by observing the draw at drains at the time of inspection. Nonetheless, blockages will still occur in the life of any system.

RЛ	วเท	I in	•
IVI	alli	Line	☞.

Pressure: Water pressure appears adequate.

Supply Lines:

"Above the Res	k. o		
	Material: Condition:	Not all visible. Copper, Combination of materials. OK MM RR NI □ □ □ ☑	
Waste	Lines: Material: Condition:	Plastic, Combination of materials.	
Hose I	Bibs / Hookups: General:		
connect pan sho Imprope	ted to a drain line of	of valve at the upper portion of the water heater is a required safety valve which show the oper size terminating just above floor elevation. If no drain is located in the floor a drain extending to a safe location. The steam caused by a blow-off can cause scal e corrected.	catcl
Power S	Source:	ere is a special demand twater system installed sich provides instant hot atter. This unit appears anctional.	
	Location:		
	Condition:		
Fuel S	ystem:		
	Meter / Tank:	☑ □ □ □ Oil Tank. □ □ □ ☑ Lines not fully visible, tank not fully visible.	







Septic System:		
	OK MM RR NI	

System Condition: \square \square \square Private waste systems/sewers are not included in this inspection. This is to be done by a separate licensed contractor.

See Bathrooms section of report for information about plumbing and fixtures in those areas.

Fixtures & Drain

Kitchen Sink: ☑ □ □



KITCHEN - APPLIANCES

We may test kitchen appliances for basic functionality, but cannot evaluate them for their performance nor for the variety of their settings or cycles. Appliances older than ten years may exhibit decreased efficiency. Even if general comments are made, these items are not inspected: free-standing appliances, refrigerators, freezers, ice makers, trash-compactors, built-in toasters, coffee-makers, can-openers, blenders, instant hot-water dispensers, water-purifiers, barbecues, grills, or rotisseries, timers, clocks, thermostats, the self-cleaning and cooking capability of ovens, and concealed or countertop lighting, which is convenient but often installed after the initial construction and not wired to national electrical standards. These items should be considered outside the scope of the inspection. Appliances are not moved during the inspection. Portable dishwashers are not inspected, as they require connection to facilitate testing.

Range/ Cooktop / Oven: Type & Condition:	V		
Ventilation: <i>Type & Condition:</i>	V		
Refrigerator: Type & Condition:	V		





				No. of the last of	The case is	
Dishwa	sher:	OK		D.D.	N.II	
	Condition:	OK ☑	MM	KK □	INI	
	ge Disposal: Condition:	$\overline{\square}$				
	Built-ins: Microwave:	V				
			В	A ₁	ГНІ	ROOMS
evaluate usually inspecto Our insp represer	e window treatments, steam sho the responsibility of a termite ors will not leak-test second floor dection of interior areas includentative number of windows and	owers inspe show es the door	s, and ector. wer p ne vis	d sau How ans v sually	unas. vevei witho y acc es ar	not comment on common cosmetic deficiencies, and do not. More importantly, we do we leak-test shower pans, which is r, because of the possibility of water damage, most termite out the written consent of the owners or occupants. cessible areas of walls, floors, cabinets and closets, and and outlets. We do not evaluate window treatments, nor moved we do not comment on common cosmetic deficiencies.
	Cabinetry:		n oab	111010	, and	a we do not comment on common cosmette denoichates.
	Master Bath:					
	Hall Bath:	\checkmark				
	Upstairs Bath	\checkmark				
	Basement Bath:	\checkmark				
Toilet:						
	Master Bath:	\checkmark				
	Hall Bath:	$\overline{\mathbf{A}}$				
	Upstairs Bath	$\overline{\mathbf{Q}}$				
	Basement Bath:	$\overline{\mathbf{A}}$				
	ower Fixtures: Master Bath:	Ø				

_					
Α	d	d	re	SS	:

	Upstairs Bath	OK ☑	MM	RR □	NI □	
	Basement Bath:	$\overline{\mathbf{A}}$				
Tub/Sh	nower And Walls: Master Bath:	☑				
	Upstairs Bath					Cracked gel coat in upstairs bathtub.
				T		
	Basement Bath:					
Bath V	'entilation: Master Bath:	\square				
	Hall Bath:	$\overline{\checkmark}$				
	Upstairs Bath	$\overline{\checkmark}$				
	Basement Bath:	V				

INTERIOR ROOMS

Our inspection of living space includes the visually accessible areas of walls, floors, cabinets and closets, and the testing of a representative number of windows and doors, switches and outlets. We do not evaluate window treatments, move furnishings or possessions, lift carpets or rugs, empty closets or cabinets, nor comment on cosmetic deficiencies. We may not comment on cracks that appear around windows and doors, along lines of framing members or along seams of drywall and plasterboard. These are typically caused by minor movement, such as wood shrinkage, common settling, and seismic activity, and will often reappear if they are not correctly repaired. Such cracks can become the subject of disputes, and are therefore best evaluated by a specialist. Floor covering damage or stains may be hidden by furniture, and the condition of floors underlying floor coverings is not inspected. Determining the condition of insulated glass windows is not always possible due to temperature, weather and lighting conditions. Check with owners for further information. All fireplaces should be cleaned and inspected on a regular basis to make sure that no cracks have developed. Large fires in the firebox can overheat the firebox and flue liners, sometimes resulting in internal damage. Testing, identifying, or identifying the source of environmental pollutants or odors (including but not limited to lead, mold, allergens, odors from household pets and cigarette smoke) is beyond the scope of our service, but can become equally contentious or difficult to eradicate. We recommend you carefully determine and schedule whatever remedial services may be deemed advisable or necessary before the close of escrow.

General Comments:

An occupied house such as this one will typically have furniture, storage and other items that will partially block areas from inspection. Closets are usually packed with items which can completely block access and/or inspection. It is recommended that you inspect these areas at the walk through before your closing. Report any adverse findings to your representative prior to closing. The general condition of the home was satisfactory. Excluding normal wear and tear.

D	O	O	r	•	•
$\boldsymbol{-}$	v	v		J	

Overall Interior Door Condition:		
Master Bath:		

	OFF Francis Francis					Page 26
Home "Above the I	Inspections Eraser Free	Inspect	ion:			Address:
		OK	MM	RR	NI	
	Hall Bath:					
	Upstairs Bath					
	Basement Bath:					
Windo	ows:					
	General Type & Condition:	\square				Unless noted elsewhere it this report.
	Master Bath:	\square				
	Upstairs Bath	\square				
	Basement Bath:	\square				
Walls	:					
	General Material & Condition:	\square				
	Master Bath:	\square				
	Hall Bath:	\square				
	Upstairs Bath	\square				
	Basement Bath:	\square				
Ceilin	gs:					
	General Type & Condition:		V			Crack noted on ceiling above entryway next to garage (outside o half bath).
		*			,	
	Master Bath:	\square				
	Hall Bath:	\square				
	Upstairs Bath					
	Basement Bath:					
Floors						
	General:	\square				Typical wear and tear noted. Rugs and floor coverings preven viewing of primary floor materials.
	Master Bath:	\square				
	Hall Bath:	\checkmark				

Condition: **Smoke / Fire Detector:**

General:

Stairs & Handrails:

Upstairs Bath

Basement Bath:

 \checkmark

 \checkmark

 $\overline{\mathbf{V}}$

 \checkmark

Storage filled.

Closets:

Home Inspections "Above the Rest" **	nspeci	ion:			Address:
Comments:		Ø			Smoke and fire detectors have a limited life span of @ 10 years Replacing older units for safety is suggested.
Carbon Monoxide Detector:					
Comments:	OK	MM ☑	RR	NI	Add to all sleeping areas. At least one per level of the home.
		LA	UN	ID I	RY AREA
them cannot be judged. Drain lines a	nd wat	er su	pply	valve	spection and the condition of any walls or flooring hidden by es serving washing machines are not operated. Water supply g and Electrical pages for more details about those types of
Laundry:					
Location:	Bas	ement	i.		
Hose Bibs / Hookups/Sink Fauce Laundry:	ets: ☑				Turn valve(s) off after use when not using the washing machine.
					This could prevent any possibility of water leaking into the home.
Dryer Vent: Laundry:	Ø				Clean venting before first use and at least annually to prevent dryer fires.
			60		